May 1, 2013 7:27:17 AM

Required Date: 4/30/13

Item ID:

D3016-13

Accept

Revision ID:

Item Name:

Bracket

Start Date:

4/30/13

Start Qty: 10.00

Req'd Qty: 10.00

10 *15 *

Reference:

Approvals:

Quality Control

Process Plan:

OC:

Date/3-05-/

Tooling:

Date:

SPC (Y/N):

Sco a Work Center ad	Tor Secreption	
Draw Nbr	Revision Nbr	
D3016	Rev A	
100		0.00
100	FLOW WATER JET	
Waterjet	Memo	0.00
FLOW CNC Waterjet	I-Cut as per Dwg D Dwg Rev: A Prog Rev: A	
	2-Deburr if necessar	у
110	QC2- Inspect parts off machine I	FAI/FAIB 0.00
110		
QC	Memo	0.00

N900040100 Setup Start *NS1* Stop *NS2*

Cust Item ID: Customer:

Date:

Run Start *NR1*

Stop *NP2*

Top a section Region Region repu Com Qiy Qiy Number section

15

A. 13.08.01

15 0

Ae 13.08.01

			DQA:	Date:	
NCR:	Yes / No	WORK ORDER NON-CONFORMANCE / UPDATE			

									,		QA Closed:	Dat	e:	
Work Orde	er:		=:-			DISPOSITION				AGAINST D	EPARTMENT	/PROCESS		
						Rework Scrap		1	Skid-tube Machining	Crosstube Small Fab	⊣	Water Jet d. Eng. Coor.		Engineering Quality Other
NCR I	No.					Use-as-is Work Order Update	 		noforming Large Fab	FinishingComposite	Rec/stol	re/Packaging Supplier		Other
Root					Descri	ption of work order update	In	itial	Ac	tion	Sign &			
Cause		Date	Step	Qty		or Non-conformance	Chie	f Eng	Desc	ription	Date	Verification	1	QC Inspector
Doc/Data														
Equip/Tooling				1								ł		
Operator														
Material					ļ									
Setup														
Other													1	
Process							1					1		
Supplier														
Training														
Unapproved			<u> </u>	l	<u> </u>						<u> </u>			
							AULT	CATE	GORY					
Landi		ı				General	_ 1			۲-	_	٠ ,		
		Bending				Bend	-	irain			Ovalized			ressure/Forced
		Centre No	ot Concer	ntric to	O/S	BOM/Route	—	lardwa			Over/Under		_	emperature/Cure
	-	Cracks				Broken/Damaged	_		ion Incomplete		Part Incorre			Veld
	Щ	Crushed/0	Crimped.		<u> </u>	Burrs	\vdash		ions Incomplete,	/Unclear	Part Lost/M	-		Vrong Stock Pulled
		Cuffs				Contamination	\vdash		enance	<u> </u>	Part Moved			
		Heat Trea				Countersink	├ ──┤	Aislabe		<u> </u>	Positioned			
	igspace	Inspection		Tube		Cut Too Short		Aisread	d	L	Power Loss,	/Surge	IC	other
	ldash	Ripples in				Drill Holes	\vdash	Offset						
		Torque W		xtrusio	n	Drawing	1		Calibration					
	Turning Sequence		Finish		Out of 9	Sequence								

Outside Dimensions

Wave/Twist in Tube

Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Work Order ID 100818

May 1, 2013 7:27:17 AM

100818

may 1, 2015 7	.27.17 AW			Ţ				
Item ID: Revision ID:	D3016-13		Acco	ept	*N90004	೧1 ೧೧*	-	NS1*
Item Name:	Bracket						Stop *	NS2*
Start Date:	4/30/13	Start Qty: 10.00	*10*		Cust Item ID:			
Required Date	e: 4/30/13	Req'd Qty: 10.00	*10*		Customer:			
Reference:				1				
Approvals:	Process P	Plan: Dat	e: To	ooling:	Date:		Run Start 🛧	NR1*
	QC:	Dat		C (Y/N):	Date:		Stop *	NR2*
Seeger 10 Work Center	·n	Speration Description		Ses Fig/ Run Hours	Tool H: Toel	# Pian Acce Code Qty	pv Reject Rejec Qty Numb	
120		QC8- Inspect parts - second chec	sk (0.00	- I			
120 QC Quality Control		Memo		0.00	i 	Ć	०,४०-६०	ı ŠP
Quanty Control				1				
130			(0.00	!		Ž	opo
<u>*130*</u>		NC BRAKE		0.45			¥	V
Brake NC Brake NC		Memo Form D3016-13 as		0.00	,		(19)	20 13 look
					: 			
140		QC5- Inspect part completeness	to step on W/O (0.00				
*14 0 *		Memo		0.00	!		(4) 13.06	dl ar
Quality Control					}			_

NCR: Yes / No

WORK ORDER NON-CONFORMANCE / UPDATE

DQA: 13/08/13

									QA Closed:	Unite:	10/8/12
Work Orde	r: 100	818	-	•	DISPOSITION	_		AGAINST DE	PARTMENT	/PROCESS	
	o. <u>D30</u>		•		Rework Scrap V Use-as-is Work Order Update	Machining Small Fab s-is Thermoforming Finishing ate Large Fab Composite			4	Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other
Root				Descri	ption of work order update	Initial	Act	ion	Sign &	•	
Cause	Date	Step	Qty		or Non-conformance	Chief Eng	Descr	iption	Date	Verification	QC Inspector
Doc/Data Equip/Tooling Operator Material Setup Other Process Supplier Training Unapproved	13.000	100	1	حسكانه	more when I have bloom Down I openherm.	0AS 16 9-5 037247 17/06/02		o replace	Az 13.08.02	OAS OS UB-OB-OD	0AS 16 26 052412 13/08/02
S.I.S.F.I.			<u> </u>	1	F	AULT CAT	GORY		<u> </u>		
Landin	g Gear				General				_		_
	Bending Centre No Cracks Crushed/G Cuffs Heat Trea	Crimped		o/s	Bend BOM/Route Broken/Damaged Burrs Contamination Countersink	Instruc	tion Incomplete tions Incomplete/l enance		Ovalized Over/Under Part Incorre Part Lost/M Part Moved Positioned \	ct	Pressure/Forced Temperature/Cure Weld Wrong Stock Pulled
	Inspection	n Strip in	Tube		Cut Too Short	Misrea	od		Power Loss/	'Surge	Other
	Ripples in	Bend			Drill Holes	Offset				 	
[Torque W	aves in E	xtrusio	n 🗀	Drawing	⊢ ⊣	Calibration				
				Finish	Out of	Sequence					
1 1				Folio	Outsid	e Dimensions					

Page 3

May 1, 2013 7:27:17 AM Item ID: D3016-13 Accept *N900040100* Setup Start Revision ID: Item Name: Bracket 4/30/13 *10* Start Qty: 10.00 Start Date: Cust Item 1D: Req'd Qty: 10.00 Required Date: 4/30/13 *10* **Customer:** Reference: Run Process Plan: Approvals: Date: Tooling: Date: OC: Date: SPC (Y/N): Date: is one IE. . 1.0 Reject ិ នោ Reject Βí Accept. Work center is Description Qty -Number Stamp Kon Hours Code Qty 150 0.00 Packaging *150* EZ 13-8-2 Packaging 0.00Memo Packaging Identify and bag with light oil (Vactra oil #2), then *****STOCK IN LARGE Location: WA or 1 160 QC21- Final Inspection - Work Order Release 0.00 *160* QC 0.00 Memo MUJ13-08-09 Quality Control

A CON.

									•		DQA:	Date:	
NCR:	⁄es	/ No				WORK ORDER NON-	cor	VFORM	MANCE / UPI	DATE	OA Clasadi	Date	
											QA Closed:	Date:	
Work Orde						DISPOSITION				AGAINST D	EPARTMENT,	/PROCESS	
work Ordi	er.				······································	Rework	7	1	Skid-tube	Crosstube	7	Water Jet	Engineering
Part N	J۸					Scrap	-	1	Machining	Small Fab	Pro	d. Eng. Coor.	Quality
, a.c.	•••					Use-as-is	1		noforming	Finishing		re/Packaging	Other
NCR N	lo.					Work Order Update	1		Large Fab	Composite		Supplier	1 1
											-		
Root						iption of work order update		Initial	_	tion	Sign &		
Cause		Date	Step	Qty		or Non-conformance	Ch	nief Eng	Desci	ription	Date	Verification	QC Inspector
oc/Data													
quip/Tooling				,				ļ					
perator	\dashv											•	
1aterial						•		1					·
etup													
ther rocess	\dashv												
upplier	_												
raining	_							İ					
napproved								I					
		· · · · · · · · · · · · · · · · · · ·				1	AUI	LT CATE	GORY				
Landi	ng G	ear				General		-	•	_		_	_
		Bending				Bend		Grain			Ovalized	_	Pressure/Forced
		Centre No	t Concer	ntric to (o/s	BOM/Route	ļ	Hardwa		Ļ	Over/Under	-	Temperature/Cure
		Cracks			-	Broken/Damaged	\perp	4	ion Incomplete	. L	Part Incorre	<u>-</u>	Weld
	_	Crushed/C	Crimped		<u> </u>	Burrs		-1	ions Incomplete/	Unclear	Part Lost/Mi	_	Wrong Stock Pulled
		Cuffs			-	Contamination	_	Mainte		ļ.	Part Moved		
		Heat Treat		T L.:		Countersink	-	Mislabe		}-	Positioned V		Other
	-	Inspection		oauı	-	Cut Too Short Drill Holes	-	Misread Offset	ı	L	Trower ross/	oulge [Other
		Ripples in Torque W		vtrucios	, <u> </u>	Drawing	-	4	Calibration				
,		Turning Se		ACI USIUI	` -	Finish		-	Sequence				
	\dashv	Wave/Twi	-	e		Folio	-	┫	Dimensions				

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Work Order ID:

100818

Parent Item:

D3016-13

Parent Item Name:

Bracket

Comments:

M4130NS.049

4130 Sheet .049

IPP B03.05.09ReformatKJ/RF

IPP Rev:C Now On Waterjet 07-10-23 JLM Verified BY: EC

Component Item ID/ Item Name

Replacement Item ID

Mfg/ Purch

Purchased

Bin Item

No

Primary Location

Last

Location

Measure Hand sf

Unit of

128.2903

Loc Code

Qty on

Start Date: 4/30/13

Start Qty: 10.00

0.243

Qty per Kit Total

Qty

Date

Issued

Required Date: 4/30/13

Required Qty: 10.00

Qty

Issued

Page 1

Status

Location

.

الالالا 124283

Loc Oty 128,290363

† 1**0**0

Route

Seq ID

÷ 2

...340263 106.75

									DQA:	Date:	
NCR: Yes	/ No				WORK ORDER NON-C	CONFORM	MANCE / UP		QA Closed:	Date:	
Work Order:			-		DISPOSITION			AGAINST DE	PARTMENT	PROCESS	
Part No.					Rework Scrap Use-as-is Work Order Update	4 1	Skid-tube Machining noforming Large Fab	Crosstube Small Fab Finishing Composite	+	Water Jet d. Eng. Coor. e/Packaging Supplier	Engineering Quality Other
WERT ITO.						1					i i
Root			1	Descr	iption of work order update	Initial	Ac	ction	Sign &		
Cause	Date	Step	Qty		or Non-conformance	Chief Eng	Desc	ription	Date	Verification	QC Inspector
Ooc/Data equip/Tooling Operator Waterial Setup Other Process Supplier											

Landin	g G	Sear		General	_		 -
ſ		Bending		Bend	Grain	Ovalized	Pressure/Forced
ſ		Centre Not Concentric to O/S		BOM/Route	Hardware	Over/Under tolerance	Temperature/Cure
F		Cracks		Broken/Damaged	Inspection Incomplete	Part Incorrect	Weld
Γ		Crushed/Crimped.		Burrs	Instructions Incomplete/Unclear	Part Lost/Missing	Wrong Stock Pulled
Γ		Cuffs		Contamination	Maintenance	Part Moved	
Γ		Heat Treat		Countersink	Mislabeled	Positioned Wrong	 _
Γ		Inspection Strip in Tube		Cut Too Short	Misread	Power Loss/Surge	Other
		Ripples in Bend		Drill Holes	Offset		
Γ		Torque Waves in Extrusion		Drawing	Out of Calibration		
		Turning Sequence		Finish	Out of Sequence		
		Wave/Twist in Tube	٦	Folio	Outside Dimensions		

FAULT CATEGORY

Unapproved

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

DART AEROSPACE LTD	Work Order:	100816
Description: Bracket	Part Number:	D3016-13
Inspection Dwg: D3016 Rev: A		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X	First Article		Prototype
---	---------------	--	-----------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
·					opootion	
4.000	+/-0.010	4.000			V	JKM-01
2.983	+/-0.010	2.983	-		_v	
2.401	+/-0.010	2.401			V	
2.250	+/-0.010	2.250	-		V	
	:					
					<u> </u>	
					<u> </u>	
					= =-	
				-		
					<u> </u>	
			-			
	-					
					<u> </u>	
		_		<u> </u>		
					<u> </u>	

Measured by:	Ae	Audited by:	PD	Prototype Approval:	N/A
Date:	13.08.01	Date:	13-68-01	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	07.11.23	New Issue	KJ/EC/DD	<i>X</i>
				-

		•
b ,		



DART

DESIGN	P	DRAWN BY	DART AEROSPAC HAWKESBURY, ONTARIO, C.	
CHECK	ED 4	APPROVED	DRAWING NO. D3016	REV. A SHEET 1 OF 3
DATÉ			TITLE	SCALE
01.0	5.18	<u>,</u>	SEAT FRAME ASSEMBLY	NTS
A		01.05.18	NEW ISSUE	


160818

QTY	PART NUMBER	DESCRIPTION	MATERIAL
Х	D3016-041	SEAT FRAME ASSEMBLY	N/A
1	D3016-1	TUBE	AISI 4130N TUBE, Ø0.75 DIA x 0.049 WALL (M4130N-T0750W049)
2	D3016-3	TUBE	AISI 4130N TUBE, Ø0.75 DIA x 0.049 WALL (M4130N-T0750W049)
1	D3016-5	TUBE	AISI 4130N TUBE, Ø0.50 DIA x 0.049 WALL (M4130N-T0500W049)
2	D3016-7	TUBE	AISI 4130N TUBE, Ø0.50 DIA x 0.049 WALL (M4130N-T0500W049)
1	D3016-9	SADDLE	AISI 4130N TUBE, Ø1.00 DIA x 0.120 WALL (M4130N-T1000W120)
1	D3016-11	SADDLE	AISI 4130N TUBE, Ø1.00 DIA x 0.120 WALL (M4130N-T1000W120)
1	D3016-13	BRACKET	AISI 4130N SHEET, 18 GAUGE (M4130N-S049)
1	D3016-15	GUSSET	AISI 4130N SHEET, 18 GAUGE (M4130N-S049)
1	D3016-17	GUSSET	AISI 4130N SHEET, 18 GAUGE (M4130N-S049)
2	D3020-1	FITTING	N/A

NOTES

- 1) _WELD PER DART QSI 004 --
- 2) ON SHEET METAL PARTS, BREAK ALL UNMARKED CORNERS 0.020-0.040
- 3) FINISH: POWDER COAT GREY SANDTEX (REF. 4.3.5.6) PER DART QSI 005 4.3
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED


DEO ATTACHED




Copyright © 2001 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.


•		
,		
**.		



			,	



		•
•		



A * * *		